/ \	Manufacturing Work Instruction					Pg 1 of 7		
INSPIRED FLIGHT	101698		IF1200	Station	Phase			
Date	Rev	Title	Title					
2/23/22	А	IF120	1200 - Installing 101824, 101826 - Folding Props					

Engineer: Tyler VanDenBerg

Approved Engineering: C.Elder **Approved Manufacturing:**

Revision History:

Date	Rev	ECO#	Description
2/23/22	А		Initial Release

/ \			Manufacturing	Pg 2 of 7				
INSPIRED FLIGHT	101698		IF1200	Station	Phase			
Date	Rev	Title	Fitle					
2/23/22	А	IF1200	1200 - Installing 101824, 101826 - Folding Props					

Parts Required:

Item No.	Part No.	Description	LOC	Qty
1	101824	ASSY, FOLDING PROP, 18.5X6.3, CW		3
2	101826	ASSY, FOLDING PROP, 18.5X6.3, CCW		3

/ \			Manufacturing	Pg 3 of 7				
INSPIRED FLIGHT	101698		IF1200	Station	Phase			
Date	Rev	Title	Fitle					
2/23/22	А	IF1200	-1200 - Installing 101824, 101826 - Folding Props					


Tools Required:

Hardware:	Consumables:
.9 Nm - 2.5mm Male Hex Torque Driver	
Blue Loctite	

	Manufacturing Work Instruction							
INSPIRED FLIGHT	101698		IF1200	Station	Phase			
Date	Rev	Title	itle					
2/23/22	Α	IF120	200 - Installing 101824, 101826 - Folding Props					

Procedure:

Step 1: Apply blue loctite to the four motor mounting screws.




	Manufacturing Work Instruction					Pg 5 of 7		
INSPIRED FLIGHT	101698		IF1200	Station	Phase			
Date	Rev	Title	itle					
2/23/22	Α	IF1200	1200 - Installing 101824, 101826 - Folding Props					

Step 2: Make sure the torque driver is set to .9Nm



/ \	Manufacturing Work Instruction					Pg 6 of 7		
INSPIRED FLIGHT	101698		IF1200	Station	Phase			
Date	Rev	Title	Title					
2/23/22	Α	IF120	1200 - Installing 101824, 101826 - Folding Props					

<u>Step 3:</u> Mount the propeller assembly to the motor. Make sure the propeller direction (noted below) is mounted on the correct motor.



/ \		Manufacturing Work Instruction				Pg 7 of 7		
INSPIRED FLIGHT	101698		IF1200	Station	Phase			
Date	Rev	Title	itle					
2/23/22	Α	IF120	1200 - Installing 101824, 101826 - Folding Props					

QA Checks

• Make sure the propeller direction (noted below) is mounted on the correct motor.



